

Confidential

7

September 19, 1975

MEMO FOR FILING

Re: Emerald Mine (clay) #43-023-001
Sec. 28, T. 14 S., R. 11 W.
Juab County, Utah

On September 19, 1975 field inspection of the Emerald Mine was made to look at the viability of the operators reclamation plans.

Located in a remote location in Juab County, the clay mine has already begun some extractive operations. No live streams are in the area and no overland flow from the site is apparent.

Vegetation is mixed grass and desert shrub with prolific halogeton. Estimated precipitation is 8 to 12 inches annually.

The operator proposes to remove and stockpile his loose surficial material and overburden. When finished stripping out the clay vein, the operator will regrade the pit walls and overburden stockpiles, finally spreading surficial material over the disturbed area.

At this point, no revegetation is planned.

The operator has been contacted for his site map and section diagram of regrading.



RONALD W. DANIELS
COORDINATOR OF MINED LAND
RECLAMATION

RWD/lc

ROLLING FIELD.

Yes: Yes:

Curvy/Bend:



9-19-75

Fall River Clay Mining Co. 14S 11W
Filtrol Corp. Viewed from
west.

TOE HUNG
CLAY ID
VIEW
FALL RIVER
CLAY MINING
CORP.
VIEWED FROM
WEST

A 511486

9/19/75

Fall River Clay Mining Co. 14S 11W
Filtrol Corp. First workings
main pit & stockpiling area

A 511486

Quincy Bank